
## KNOW YOUR Wear Metals (Fe)





The presence of Iron (Fe) is an indicator of wear of:

## **Hydraulics**

Iron

55.845

Rods, Cylinders, Gears

26



Engines Cylinder Liners, Rings, Camshaft, Gears, Camshaft, Valve Train, Oil Pump Gear & Wrist Pins



## **Transmissions**

Gears, Disks, Housing, Bearings, Brake Bands,



## Gears

Gears, Bearings, Shaft, Housing



Contact info.africa@intertek.com www.intertek.com/ocm/wear-metals/

